



## Gas Analysis Results


Customer Name: Quality Extractions  
2533 Tracy Road  
Northwood, OH 43619

Product: Propane  
Sample ID: PROPANE Lot 092623-100P  
Project Name: Liquid Phase

Date Sampled: 1-Sep-24  
Date Analyzed: 5-Dec-24

<u>Test Description</u>	<u>Method</u>	<u>Wt% Result</u>	<u>Detection Limit</u>
Methane	ASTM D2163	0.00	0.01
Ethane	ASTM D2163	0.01	0.01
Propane	ASTM D2163	99.86	0.01
n-Butane	ASTM D2163	0.03	0.01
Isobutane	ASTM D2163	0.11	0.01
n-Pentane	ASTM D2163	0.00	0.01
Isopentane	ASTM D2163	0.00	0.01
n-Hexane	ASTM D2163	0.00	0.01
Neopentane	ASTM D2163	0.00	0.01


Notes: No BTEX Detected (<1 ppm)

Signed:   
\_\_\_\_\_  
David J. Balazs

Date: 12/8/2023

Current Chromatogram(s)

FID1 A, Front Signal (12082023\Propane Lot # 092623-100B (1) 2023-12-08 12-59-39.D)



QUALITY EXTRACTIONS  
PROPANE  
LOT # 092623-100P